2020 年度 景林邨 消防年檢 維修工程 完工報告

景楠樓

1)換新 9L 水劑滅火筒(中國製)

原因:超過五年期

位置:G/F 升降機大堂(1 支)




位置:R/F C 梯(1 支)



2)換新 4.0 kg 粉劑滅火筒(中國製)

原因:超過五年期

位置:G/F 電話機房(1 支)



3) 換新 5.0 kg CO2 滅火筒(中國製)

原因: 10/2020 便到五年期, 需於 31/10/2020 前更換


位置:G/F總電掣房(1 支)



4)換新 2.0 kg 粉劑滅火筒(中國製)

原因:8/2020 便到五年期, 需於 31/08/2020 前更換

位置:G/F 大堂(1 支)



5)換新射咀箱之玻璃

原因:損壞

位置:01-07 翼-28/F、18/F、15/F(3 塊)

位置:08-14 翼-23/F(1 塊)

位置:15-21 翼-31/F、26/F(2塊)



6)換新扲手掣(KAC)

原因:故障

位置:01-07 翼-9/F、6/F、3/F (3 個) 位置:08-14 翼-21/F、10/F (2 個)

位置:15-21 翼-13/F (1 個)













7)換新警鐘(220V)

原因:故障

位置:08-14 翼-30/F、26/F(2 個)

位置:15-21 翼-14/F(1 個)







8)換新龍頭白膠圈

原因:老化


位置:01-07 翼(34 個)







































位置:08-14 翼-(34 個)





































































位置:15-21 翼(34 個)





































































9)換新膠射咀 原因:損壞

位置:08-14 翼-9/F(1 個)



10)換新龍頭唐環

原因:損壞

位置:15-21 翼-30/F(1 個)



11)將消防分層閘掣加鎖、鏈、警告牌、封鎖編碼帶、FS251 証書

位置:17/F 消防泵房(6套)











12)換新 40mm 減壓掣一個連 40 mm 消防喉約 3 米, 40 mm 閘掣兩個連配件, 拆除及重裝修口板

原因:水壓不足

位置:位置:08-14 翼-23/F(1 單)



景棉樓

1)換新 5.0 kg CO2 滅火筒(中國製)

原因:超過五年期

位置:R/F 升降機房(1 支)



2)換新 9L 水劑滅火筒(中國製)

原因:超過五年期

位置:G/F 垃圾房(1 支)



3)換新喉轆拉輪

原因:損壞

位置:01-08 翼-29/F、27/F、26/F、28/F、15/F、13/F、4/F(7個)



位置:09-16 翼-34/F、33/F、32/F、29/F、28/F、26/F-19/F、17/F-9/F、7/F-4/F、2/F(27 個)











位置:17-27 翼-31/F、28/F、24/F、22/F、20/F、17/F、16/F、14/F、13/F、12/F、10/F、8/F、6/F、3/F、2/F(15 個)































4)換新扲手掣(KAC)

原因:故障

位置: 01-08 翼-17/F(1 個) 位置:17-27 翼-24/F(1 個)





5)換新射咀箱連玻璃及鎖

原因:損壞

位置:01-08 翼-29/F、24/F(2 套)





6)換新射咀箱之玻璃

原因:損壞

位置:01-08 翼-16/F、12/F、5/F(3 塊)

位置:09-16 翼-31/F、13/F(2 塊)







位置:01-08 翼-29/F(1 個) 位置:09-16 翼-23/F、6/F(2 個)







8)換新龍頭唐環

原因:損壞

位置:01-08 翼-18/F(1 個) 位置:09-16 翼-30/F(1 個)





9)換新警鐘 (220V)

原因:故障

位置:01-08 翼-32/F(1 個)



10)換新 6 分氣昇

原因:故障

位置:01-08 翼-34/F (1 個) 位置:17-27 翼-34/F (1 個)





11)新加裝"消防入水掣"金屬指示牌仔連入水掣指示牌

原因:欠缺 位置:G/F(3 套)







12)換新 80mm 吸入式(2 吋泡水)龍頭連龍頭系統入水工作

原因:損壞

位置:01-08 翼-30/F、25/F、23/F、11/F、10/F、9/F(6個)













位置:09-16 翼-26/F、18/F、13/F、12/F、10/F、4/F 6 個)



位置:17-27 翼-31/F、30/F(2個)



13)換新龍頭白膠圈

原因:老化

位置:09-16翼-29/F、25/F、21/F、11/F、7/F(5個)











14)換新 40mm 減壓掣連入水工作

原因:故障

位置:01-08 翼-31/F (1 個) 位置:17-27 翼-7/F (1 個)





15)將消防分層閘掣加裝鎖、鏈、警告牌、封鎖編碼帶、FS251 証書

位置:17/F 消防泵房、





16) 換新 25mm 喉轆**喉約** 1 **米**, 25 mm 閘掣 1 個連配件及喉轆系統放入水工作

原因:霉爛

位置: 09-16 翼-23/F (6 套)



景桃樓

1)換新 4.0 kg 粉劑滅火筒(中國製)

原因:超過五年期

位置:G/F 大堂保安内電掣房(1 支)



2) 換新 5.0 kg CO2 滅火筒(中國製)

原因:10/2020 便到五年期, 需於 31/10/2020 前更換

位置:R/F 升降機房(1 支) 位置:G/F 發電機房(1 支)





3)換新喉轆拉輪

原因:損壞

位置:01-11 翼-32/F、31/F、21/F、16/F、10/F(5 個)











位置:12-19 翼-28/F、19/F、1/F(3 個)







位置:20-31 翼 34/F、32/F、31/F、28/F、26/F、25/F、22/F、13/F(8 個)

















4)換新新警鐘(220V)

原因:故障

位置:12-19 翼-27/F(1 個) 位置:20-31 翼 3/F(1 個)





5)換新膠射咀

原因:損壞

位置:01-11 翼-27/F(1 個) 位置:20-31 翼 7/F(1 個)





6)換新扲手掣(KAC)

原因:故障

位置:01-11 翼-15/F、11/F、3/F(3 個)

位置:20-31 翼-32/F(1 個)









7)換新射咀箱之玻璃

原因:損壞

位置:01-11 翼-1/F(1 塊) 位置:12-19 翼-29/F(1 塊) 位置:20-31 翼 G/F(1 塊)







8) 換新 80mm 吸入式單龍頭連龍頭系統入水工作

原因:損壞

位置:01-11 翼-33/F(1 個) 位置:20-31 翼-33/F(1 個)





9)換新 22 吋喉轆盤連紅色膠喉

原因:故障

位置:01-11 翼-9/F(1 套) 位置:12-19 翼-22/F(1 套) 位置:20-31 翼-11/F(1 套)







10) 換新喉轆 25 mm 閘掣連喉轆系統放入水工作

原因:損壞

位置:20-31 翼-12/F(1 個)



11)提供人手及工具維修扲手掣線路

原因:故障

位置:20-31 翼-25-34/F 高組(1 單) 位置:20-31 翼-14-24/F 中組(1 單)







12)將消防分層閘掣加裝鎖、鏈、警告牌、封鎖編碼帶、FS251 証書

位置:17/F 消防泵房(6套)











13) 換新 25mm 喉轆喉約 1 米連配件及喉轆系統放入水工作

原因:霉爛

位置: 12-19 翼-23/F(1 單)



景榆樓

1) 新加裝 5.0 kg CO2 滅火筒(中國製)


原因:欠缺

位置:G/F 總電掣房(1 支)



2)換新 9L 水劑滅火筒(中國製)

原因:超過5年期 位置:G/F垃圾房(1支)



3)換新 2.0 kg 粉劑滅火筒(中國製)

原因:超過5年期 位置:G/F座頭(1支)




4) 換新 4.0 kg CO2 滅火筒(中國製)

原因:超過5年期 位置:G/F大堂電掣房(1支)

5



位置:G/F 泵房(1 支)



5)換新 5.0 kg CO2 滅火筒(中國製)

原因:8/2020 便到五年期, 需於 31/08/2020 前更換

位置:G/F 發電機房(1 支)



6)換新射咀箱之玻璃

原因:損壞

位置:01-07 翼-26/F、1/F (2塊)

位置:17-24 翼-21/F (1塊)







7)換新警鐘(220V)

原因:故障

位置:09-16 翼-25/F、21/F、9/F、7/F (4個)

位置:17-24 翼-23/F(1個)











8) 換新龍頭唐環

原因:損壞

位置:17-24 翼-26/F(1個)



9) 換新 80mm 吸入式(2.5 吋泡水) 龍頭連龍頭系統入水工作

原因:損壞

位置:09-16 翼-4/F(1個)



10)新加裝"減壓閥"指示膠牌仔

原因:欠缺

位置:01-07 翼-31/F、22/F、13/F、6/F (4 塊) 位置:09-16 翼-31/F、22/F、13/F、6/F (4 塊)

> 景榆樓 31年 9-16 盟



















11)新加裝''常開'' 膠牌仔

原因:欠缺

位置:01-07 翼-31/F、22/F、13/F、6/F 減壓閥 (8塊) 位置:09-16 翼-31/F、22/F、13/F、6/F 減壓閥 (8塊) (8塊)

















12) 新加裝"常關" 膠牌仔

原因:欠缺

位置:01-07 翼-31/F、22/F、13/F、6/F 減壓閥 (4塊) 位置:09-16 翼-31/F、22/F、13/F、6/F 減壓閥 (4塊) 位置:17-24 翼-31/F、22/F、13/F、6/F 減壓閥 (4塊)




景榕樓

1) 新加裝 9L 水劑滅火筒(中國製)

原因:欠缺

位置:G/F 垃圾房(1 支)



2) 換新 5.0 kg CO2 滅火筒(中國製)

原因: 10/2020 便到五年期, 需於 31/10/2020 前更換

位置:G/F 總電掣房(1 支) 位置:G/F 發電機房(1 支)





3)換新 2.0 kg 粉劑滅火筒(中國製) 原因:09/2020 便到五年期, 需於 30/09/2020 前更換 位置:G/F 座頭(1 支)




4) 換新 4.0 kg CO2 滅火筒(中國製)

原因:09/2020 便到五年期, 需於 30/09/2020 前更換

位置:G/F 大堂電掣房(1 支) 位置:G/F 泵房(1 支) 位置:G/F 電話機房(1 支)







5)換新6分氣昇

原因:故障

位置:01-07 翼-34/F(1 個) 位置:08-15 翼-34/F(1 個)





6) 換新 6 分氣昇連 25 mm 閘掣 1 個, 25mm 力古 1 個及配件

原因:故障

位置:16-21 翼-34/F(1 單)



7)換新龍頭唐環

原因:損壞

位置:08-15 翼-26/F(1個)



8) 換新 80mm 吸入式(2 吋泡水)龍頭連龍頭系統入水工作

原因:損壞

位置:08-15 翼-25/F(1個)



10) 將消防分層閘掣加裝鎖、鏈、警告牌、封鎖編碼帶、FS251 証書

位置:17/F 消防泵房 (6套)











景松樓

1)換新 9L 水劑滅火筒(中國製)

原因:損壞

位置:G/F 垃圾房 (1 支)

位置:R/FB梯 (1 支)



2) 換新 5.0 kg CO2 滅火筒(中國製)

原因: 10/2020 便到五年期, 需於 31/10/2020 前更換

位置:R/F升降機房 (1 支) 位置:G/F 總電掣房 (1 支) 位置:G/F 發電機房 (1 支)







3)換新 2.0 kg 粉劑滅火筒(中國製)

原因:12/2020 便到五年期, 需於 31/12/2020 前更換


位置:G/F 大堂 (1 支)




4) 換新 4.0 kg CO2 滅火筒(中國製)

原因:09/2020 便到五年期, 需於 30/09/2020 前更換

位置: G/F 大堂電掣房 (1 支) 位置: G/F 泵房 (1 支) 位置: G/F 大堂電話機房 (1 支)







5)提供人手及工具維修拎手掣線路

原因:故障

位置:01-16翼-10/F-19/F高組(1單)

位置:07-26 翼-G/F-9/F 低組(1 單)







6)換新龍頭白膠圈

原因:老化

位置:01-16 翼-16/F-1/F (16 個)



















7)換新膠射咀

原因:損壞

位置:01-16 翼-18/F、8/F(2 個)





8) 換新 25mm 喉轆閘掣連喉轆系統放入水工作

原因:損壞

位置:01-16 翼-18/F (1 個)



9) 新 6 分氣昇 **原因**:故障

位置:07-26 翼-19/F (1個)



景櫚樓

1)換新 5.0 kg CO2 滅火筒(中國製)

原因:損壞

位置:G/F 管理處內廁所 (1 支)



2)換新 9L 水劑滅火筒(中國製)

原因: 損壞

位置:G/F 垃圾房 (1 支)



3)換新 2.0 kg 粉劑滅火筒(中國製)

原因:超過5年期

位置:G/F 大堂 (1 支)



4) 換新 4.0 kg CO2 滅火筒(中國製)

原因:超過5年期

位置:G/F 泵房 (1 支)



5) 換新 5.0 kg CO2 滅火筒(中國製)


原因: 10/2020 便到五年期, 需於 31/10/2020 前更換

位置:R/F升降機房 (1 支) 位置:G/F 總電掣房 (1 支) 位置:G/F 發電機房 (1 支) 位置:升降機大堂 (1 支)









6)換新 9L 水劑滅火筒(中國製)

原因: 09/2020 便到五年期, 需於 30/09/2020 前更換

位置: G/F 升降機大堂 (1 支)



7) 換新 4.0 kg 粉劑滅火筒(中國製)

原因: 09/2020 便到五年期, 需於 30/09/2020 前更換

位置: G/F 大堂電掣**房** (1 支) 位置: G/F 電話機房 (1 支)





8) 換新射咀箱之玻璃

原因:損壞

位置:01-06 翼-18/F (1 塊)



9) 換新警鐘 (220V)

原因:故障

位置:01-06 翼-17/F (1個) 位置:07-26 翼-17/F、15/F (2個)







10) 換新龍頭之 25mm 唐環

原因:損壞

位置:01-06 翼-18/F (1個)



11) 換新 80mm 吸入式單龍頭連龍頭系統入水工作

原因:損壞

位置:12/F-11/F (1個)



12) 消防 1 號泵(15HP)積死, 需維修

位置:R/F (1台)







13)新加裝"減壓閥"指示膠牌仔

原因:欠缺

位置:01-06 翼-8/F (1 塊) 位置:07-26 翼-8/F (1 塊)





11)新加裝''常開'' 膠牌仔

原因:欠缺

位置:01-06 翼-8/F (2 塊) 位置:07-26 翼-8/F (2 塊)





12) 新加裝''常關'' 膠牌仔

原因:欠缺

位置:01-06 翼-8/F (1 塊) 位置:07-26 翼-8/F (1 塊)



