

華明邨 – 康明樓
消防年檢後執修工程

(1) 更換220V消防掣手

位置：近13 – 18室：34/F	
更換前 	更換後 
位置：近13 – 18室：27/F	
更換前 	更換後 

(2) 更換220V消防警鐘

位置：近13- 18室：25/F	
更換前 	更換後 

(3) 更換100mm直徑消防喉

位置：近07 - 12室：1/F 至 G/F

更換前



更換後



位置：近13- 18室：2/F 至 G/F梯底

更換前



更換後



(4) 更換40mm直徑消防喉轆喉

位置：近01 - 06室：29/F 至 28/F			
更換前		更換後	
位置：近01 - 06室：25/F 至 24/F			
更換前		更換後	
位置：近07 - 12室：18/F 至 17/F			
更換前		更換後	
位置：近07 - 12室：16/F 至 15/F			
更換前		更換後	

位置：近13-18室：33/F 至 32/F

更換前




更換後



位置：近13-18室：32/F 至 31/F

更換前



更換後



位置：近13-18室：31/F 至 30/F

更換前



更換後



位置：近13-18室：28/F 至 27/F

更換前



更換後



位置：近13 - 18室：27/F 至 26/F

更換前



更換後



位置：近13 - 18室：26/F 至 25/F

更換前



更換後



位置：近13 - 18室：21/F 至 20/F

更換前



更換後



位置：近13 - 18室：19/F 至 18/F

更換前



更換後



(5) 更換5kg 二氧化碳滅火筒

地下電話機房	
更換前 	更換後 
地下電掣房	
更換前 	更換後 
地下總電掣房	
更換前 	更換後 
天台升降機房	
更換前 	更換後 

(6) 更換2kg二氧化碳滅火筒

17/F消防泵房	
更換前 	更換後 

地下上水泵房 (2支)	
更換前 	更換後 

(7) 更換9L水劑滅火筒

地下垃圾房	
更換前 	更換後 