



A-51
300210

A-52
300210

A-53
300210

A-54
300210





12-12
400 x 2100



51F ⑫
200 × 600

840
1008

2015年12月

4100 x 500



B03F-1A

400x600



B04F-13

400

400

利
工
200x
500

C 06F-06 200x400

A 06F-06
300 x 2100



元

元村 - 04
300 * 500

A067-04
500 x 500



新



舊

二樓男衛生間

前



後



二樓樓梯下地下共2層



此大廈綜合維修工程由
港消集團有限公司承運

如有疑問聯絡:

陳生: 91325321

咪姐: 用手機打*1268

20樓窗位置及下面









後

20樓窗

前




此大廈綜合維修工程由
港消集團有限公司承建

如有疑問聯絡:

陳生: 91325321

咪姐: 用手機打*1268









後

前









前

天台樓梯平台



后

A photograph of a dilapidated rooftop terrace. The floor is a dark, cracked, and stained concrete surface. The walls are a light pinkish-beige color, showing signs of weathering and peeling paint. A green-painted baseboard runs along the bottom of the wall. In the background, a multi-story apartment building is visible under a clear sky.

前

A photograph of the same rooftop terrace after renovation. The floor is now covered in large, square, light-brown tiles with white grout. The walls are a clean, light pinkish-beige color. A blue-tiled baseboard runs along the bottom of the wall. A wooden door with a metal handle is visible on the left wall, and a metal door is on the right wall. A white downspout is visible on the left wall.

後

前

后

二樓會議室



前

后

二樓會議室



REC



此大廈綜合維修工程由
港消集團有限公司承辦

如有疑問聯絡：

陳生：91325821

咪姐：用手機打*1268

後

前









二樓男衛生間





棚及維修雨水去水喉



